

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY

No. 11823

RECEIVED FROM Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080057-1

Wastebins Dielectrically Soft

CHANGE TO
QUANTITY
RECEIVED

CONTRACT CODE NO.	DRAWING NUMBER	DWG. BASED OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	VENDOR PACKING SHEET NO.
322	1-000	120	0	13	1		ACCT. OR W.G. NO. 1 S.C. NO. 1

ED	DRAWING NO. AND DESCRIPTION	QUANTITY		REMARKS
		ACCEPTED	REJECTED	
24	730129-11 Circuit breaker 5-Amp. Sp. nec Ziltron No 752-1-5	24	1	Tested M.E. 1000 10-11-64

RECEIVED
BY

INSPECTED
BY

DATE 4-6-57

REJECTS RETURNED
ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY
2581 E. COLORADO ST., PASADENA CALIF.

No. 11829

RECEIVED FROM

DATE REC'D. 4-4-57
P.O. NO.

CHANGE TO
QUANTITY
RECEIVED

CONTRACT CODE NO.	DRAWING NUMBER	DIV., DASH OR STANDARD PART NO.	REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	VENDOR PACKING SLIP NO.
202	2-7	0	13				ACCT. C W. O. NO R
DRAWING NO. AND DESCRIPTION				QUANTITY		REMARKS	
761493 Connector Miniature				50		<i>50 - 100</i>	
						<i>100</i>	
						<i>28</i>	
						<i>W.E.B.</i>	
						<i>7/16/66</i>	

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080057-1

RECEIVED
BY *Blair, G.* APPROVED FOR RELEASE 20000418 : CIA-RDP81B0089K000500000974-
INSPECTED BY *SPG* DATE *4-8-57*
HMG-1044
REJECTS RETURNED
ON SHIP MEMO NO